



Фото 1: Установка Компрессорная Блочная (УКБ)

Фото 2: Установка Компрессорная Блочная



Фото 3: Компрессор с электродвигателем

Фото 4: Компрессор с электродвигателем

The document is issued by the company subject to its General Conditions of Service (copy available upon request and at site http://www.sgs.com/terms_conditions.htm#gen_conditions). The issuance of this report does not exonerate buyers or sellers from exercising all their rights and discharging all their liabilities under the Contract of Sale. Stipulations to the contrary are not binding on the Company. The Company's responsibility under this report is limited to proven negligence and will in no case be more than ten times the amount of the fees or commission. Except by special arrangement, samples, if drawn, will not be retained by the Company for more than three months.

The report (or certificate) reflects the results of inspection at time and place of inspection. The information stated in this report (or certificate) is derived from the results of inspection or testing procedures carried out in accordance with the instructions of our Client, and/or our assessment of such results on the basis of any technical standards, trade custom or practice, or other circumstances which should in our professional opinion be taken into account.




Фото 5: Блок контрольно измерительных приборов (КИП)



Фото 6: Система межступенчатого влагонмаслоотделения



Фото 7: Элементы компрессора (проставка, уплотнения)




Фото 8: Табличка





Фото 9: Система межступенчатого влагослоотделения



Фото 10: Система межступенчатого охлаждения газа



Фото 11: Система охлаждения и осушки газа



Фото 12: Система охлаждения и осушки газа





Фото 13: Шкафы управления и электрический



Фото 14: Шкаф управления



Фото 15: Шкаф электрический



Фото 16: Колонки заправочные



INSPECTION REPORT №.: ODC 0650-0216

LIST OF PHOTOS



Фото 17: Разводка проводок КИП



Фото 18: Компенсатор давления КД-2,8 (V-2,8 м³)

